


RCR201/5





1


RCR201/6



RCR201/56
RCR201/56A




RCR201/5
RCR201/6




2

RCR201/5




3

RCR201/6




RCR201/5




4




RCR201/6



RCR201/5



5




38



| | | | | |
|--|-------------------|-------------------|----------|--|
| | P P bar | MAX 10 0,5 MIN | 5 1 | |
| | T T °C | MAX 80 | 65 45 | |
| | | | | |

IISTR00201/5#—NEU REV2.12/2019



Not included / Non incluso / Non Inclus / Nie zawarty / No incluido / Nao incluido









1










RIFERIMENTO ALLA PIASTRELLA
REFERENCE TO THE TILE




MIN 67
MAX 89





www.grupponobili.it

PRIMA DI INIZIARE / BEFORE STARTING



PULIZIA / CLEANING

